

ABNORMAL TEST RESULT

OF MODEL NAC/NAM/NAH/NAP-40, 50, 60

1. Did Cheese Cloth or Paper Glow?

No.

2. Did Ground Fuse Open?

No.

3. Dielectric breakdown?

No.

4. Other Results?

See the following pages .

(FMEA : 2/ 3 ~ 3/ 3)

(Abnormal Test Result: ~)

There was no emission of flame, molten metal, ignition of cheesecloth, dielectric breakdown, opening of the ground fuse, other indication of a shock or fire hazard.

F M E A

Component	Mode		Comment	Output Voltage (V)
C11	Open		Normal operation.	
	Short		Circuit breaker operate. No hazard.	AVR1:0
C15	Open		Normal operation.	
	Short		Circuit breaker operate. No hazard.	AVR1:0
C41	Open		Normal operation.	
C41 (-101, -221, -331, -471, -681, -102, -222, -332, -472, -223)	Short		Circuit breaker operate. No hazard.	AVR1:0
C41 (-683, -104, -154, -224, -155)	Short		Normal operation.	
C45	Open		Normal operation.	
C45 (-101, -221, -331, -471, -681, -102, -222, -332, -472, -223)	Short		Circuit breaker operate. No hazard.	AVR1:0
C45 (-683, -104, -154, -224, -155)	Short		Normal operation.	
L11	Open	1or3	No hazard.	AVR1:0
		2or4	No hazard.	AVR1:0
	Short	1-2, 3-4	Circuit breaker operate. No hazard.	AVR1:0
R11	Open		Normal operation.	
R12	Open		Normal operation.	
R13 (Only -101, -221, -331, -471, -681, -102, -222, -332, -472, -223)	Open		Normal operation.	
R14 (Only -101, -221, -331, -471, -681, -102, -222, -332, -472, -223)	Open		Normal operation.	
R15 (Only -101, -221, -331, -471, -681, -102, -222, -332, -472, -223)	Open		Normal operation.	



F M E A

Component	Mode	Comment	Output Voltage (V)
R16 (Only -101, -221, -331, -471, -681, -102, -222, -332, -472, -223)	Open	Normal operation.	
R41	Open	Normal operation.	
R42 (Only -101, -221, -331, -471, -681, -102, -222, -332, -472, -223)	Open	Normal operation.	
R43 (Only -224, -155)	Open	Normal operation.	
R44 (Only -224, -155)	Open	Normal operation.	
Harness41	Open	Normal operation.	